



Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



055:12/07/2019
058:30/07/2019
061:23/08/2019


056:19/07/2019
059:09/08/2019

057:26/07/2019
060:16/08/2019


Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]



Angolo [gradi]



055:12/07/2019

056:19/07/2019

057:26/07/2019

058:30/07/2019

059:09/08/2019

060:16/08/2019


061:23/08/2019

Sito: PMA-FS Tubo: SSI-SP02

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 055:12/07/2019

— 056:19/07/2019

— 057:26/07/2019

— 058:30/07/2019

— 059:09/08/2019

— 060:16/08/2019



— 061:23/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



055:12/07/2019
058:30/07/2019
061:23/08/2019


056:19/07/2019
059:09/08/2019

057:26/07/2019
060:16/08/2019


Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]



Angolo [gradi]



055:12/07/2019
058:30/07/2019
061:23/08/2019

056:19/07/2019
059:09/08/2019


057:26/07/2019
060:16/08/2019

Sito: PMA-FS Tubo: SSI-SP02

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 055:12/07/2019

— 056:19/07/2019

— 057:26/07/2019

— 058:30/07/2019

— 059:09/08/2019

— 060:16/08/2019



— 061:23/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



110:12/07/2019
113:30/07/2019
116:23/08/2019

111:19/07/2019
114:09/08/2019



112:26/07/2019
115:16/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]

Angolo [gradi]



110:12/07/2019

111:19/07/2019

112:26/07/2019

113:30/07/2019

114:09/08/2019

115:16/08/2019


116:23/08/2019

Sito: PMA-FS Tubo: SSI-SP03

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 110:12/07/2019

— 111:19/07/2019

— 112:26/07/2019

— 113:30/07/2019

— 114:09/08/2019

— 115:16/08/2019



— 116:23/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



110:12/07/2019
113:30/07/2019
116:23/08/2019

111:19/07/2019
114:09/08/2019



112:26/07/2019
115:16/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]

Angolo [gradi]



110:12/07/2019
113:30/07/2019
116:23/08/2019

111:19/07/2019
114:09/08/2019


112:26/07/2019
115:16/08/2019

Sito: PMA-FS Tubo: SSI-SP03

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 110:12/07/2019

— 111:19/07/2019

— 112:26/07/2019

— 113:30/07/2019

— 114:09/08/2019

— 115:16/08/2019



— 116:23/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



110:12/07/2019

111:19/07/2019

112:26/07/2019

113:30/07/2019

114:09/08/2019

115:16/08/2019



116:23/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]

Angolo [gradi]



110:12/07/2019
113:30/07/2019
116:23/08/2019

111:19/07/2019
114:09/08/2019


112:26/07/2019
115:16/08/2019

Sito: PMA-FS Tubo: SSI-SP04

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 110:12/07/2019

— 111:19/07/2019

— 112:26/07/2019

— 113:30/07/2019

— 114:09/08/2019

— 115:16/08/2019



— 116:23/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



110:12/07/2019

111:19/07/2019

112:26/07/2019

113:30/07/2019

114:09/08/2019


115:16/08/2019

116:23/08/2019


Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Resultante spost. [mm]



Angolo [gradi]



110:12/07/2019

111:19/07/2019

112:26/07/2019

113:30/07/2019

114:09/08/2019

115:16/08/2019


116:23/08/2019

Sito: PMA-FS Tubo: SSI-SP04

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 110:12/07/2019

— 111:19/07/2019

— 112:26/07/2019

— 113:30/07/2019

— 114:09/08/2019

— 115:16/08/2019



— 116:23/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



055:12/07/2019

056:19/07/2019

057:26/07/2019

058:30/07/2019

059:09/08/2019


060:16/08/2019

061:23/08/2019


Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]



Angolo [gradi]



055:12/07/2019

056:19/07/2019

057:26/07/2019

058:30/07/2019

059:09/08/2019

060:16/08/2019


061:23/08/2019

Sito: PMA-FS Tubo: SSI-SP05

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 055:12/07/2019

— 056:19/07/2019

— 057:26/07/2019

— 058:30/07/2019

— 059:09/08/2019

— 060:16/08/2019



— 061:23/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



055:12/07/2019

056:19/07/2019

057:26/07/2019

058:30/07/2019

059:09/08/2019

060:16/08/2019



061:23/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]

Angolo [gradi]



055:12/07/2019

056:19/07/2019

057:26/07/2019

058:30/07/2019

059:09/08/2019

060:16/08/2019


061:23/08/2019

Sito: PMA-FS Tubo: SSI-SP05

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 055:12/07/2019

— 056:19/07/2019

— 057:26/07/2019

— 058:30/07/2019

— 059:09/08/2019

— 060:16/08/2019



— 061:23/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



035:12/07/2019
038:30/07/2019
041:23/08/2019


036:19/07/2019
039:09/08/2019

037:26/07/2019
040:16/08/2019


Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]



Angolo [gradi]



035:12/07/2019
038:30/07/2019
041:23/08/2019

036:19/07/2019
039:09/08/2019


037:26/07/2019
040:16/08/2019

Sito: PMA-FS Tubo: SSI-SP06

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 035:12/07/2019

— 036:19/07/2019

— 037:26/07/2019

— 038:30/07/2019

— 039:09/08/2019

— 040:16/08/2019



— 041:23/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



035:12/07/2019
038:30/07/2019
041:23/08/2019


036:19/07/2019
039:09/08/2019

037:26/07/2019
040:16/08/2019


Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]



Angolo [gradi]



035:12/07/2019

036:19/07/2019

037:26/07/2019

038:30/07/2019

039:09/08/2019

040:16/08/2019


041:23/08/2019

Sito: PMA-FS Tubo: SSI-SP06

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 035:12/07/2019

— 036:19/07/2019

— 037:26/07/2019

— 038:30/07/2019

— 039:09/08/2019

— 040:16/08/2019



— 041:23/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



035:12/07/2019
038:30/07/2019
041:23/08/2019

036:19/07/2019
039:09/08/2019



037:26/07/2019
040:16/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]

Angolo [gradi]



035:12/07/2019
038:30/07/2019
041:23/08/2019

036:19/07/2019
039:09/08/2019


037:26/07/2019
040:16/08/2019

Sito: PMA-FS Tubo: SSI-SP07

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 035:12/07/2019

— 036:19/07/2019

— 037:26/07/2019

— 038:30/07/2019

— 039:09/08/2019

— 040:16/08/2019



— 041:23/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



035:12/07/2019
038:30/07/2019
041:23/08/2019

036:19/07/2019
039:09/08/2019



037:26/07/2019
040:16/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]

Angolo [gradi]



035:12/07/2019
038:30/07/2019
041:23/08/2019

036:19/07/2019
039:09/08/2019


037:26/07/2019
040:16/08/2019

Sito: PMA-FS Tubo: SSI-SP07

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 035:12/07/2019

— 036:19/07/2019

— 037:26/07/2019

— 038:30/07/2019

— 039:09/08/2019

— 040:16/08/2019



— 041:23/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



110:12/07/2019
113:30/07/2019
116:23/08/2019

111:19/07/2019
114:09/08/2019



112:26/07/2019
115:16/08/2019

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]

Angolo [gradi]



110:12/07/2019

111:19/07/2019

112:26/07/2019

113:30/07/2019

114:09/08/2019

115:16/08/2019


116:23/08/2019

Sito: PMA-FS Tubo: SSI-SP08

Elaborazione differenziale integrale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



110:12/07/2019

111:19/07/2019

112:26/07/2019

113:30/07/2019

114:09/08/2019

115:16/08/2019



116:23/08/2019

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Spost. EST [mm]

Spost. NORD [mm]



110:12/07/2019

111:19/07/2019

112:26/07/2019

113:30/07/2019

114:09/08/2019


115:16/08/2019

116:23/08/2019


Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Risultante spost. [mm]



Angolo [gradi]



110:12/07/2019

111:19/07/2019

112:26/07/2019

113:30/07/2019

114:09/08/2019

115:16/08/2019


116:23/08/2019

Sito: PMA-FS Tubo: SSI-SP08

Elaborazione differenziale locale dal basso

Riferimento 000:30/10/2017

Diagramma polare della deviazione



— 110:12/07/2019

— 111:19/07/2019

— 112:26/07/2019

— 113:30/07/2019

— 114:09/08/2019

— 115:16/08/2019

— 116:23/08/2019